


For early model Beretta 92F frames without slide safety lug, it is recommended to install the semi-circular shim into the left grip panel as shown.
For late models with slide safety lug, discard the shim.



PRP-1001